

DECAL INSTALLATION


BE SURE TO START WITH A CLEAN, DRY SURFACE



 PUT TAPE IN TOP CORNERS OF DECAL. USE THIS TO HELP YOU LINE UP THE DECAL LEFT TO RIGHT AND UP AND DOWN.





HINGE 2. CREATE A TAPE "HINGE" BY PUTTING
A STRIP OF TAPE ACROSS ONE SIDE OF
THE DECAL. THIS HINGE CAN BE ACROSS
THE TOP, BOTTOM OR SIDES. FOR LONG
DECALS CREATE A "CENTER HINGE"
BY PUTTING A STRIP OF TAPE DOWN THE
CENTER OF THE DECAL; DOING THIS YOU
WILL BE APPLYING ONE SIDE AT A TIME.




3. THE HINGE WILL HOLD THE DECAL TO THE SURFACE. FLIP THE DECAL UP (OR TO THE SIDE DEPENDING ON THE HINGE) & THEN PEEL THE BACKING PAPER BACK, & THROW IT AWAY. ON A "CENTER HINGE" YOU WILL PEEL ONE SIDE BACK AT A TIME. THE FIRST SIDE YOU'LL HAVE TO CUT THE BACKING PAPER OFF.

YOU WILL BE LEFT WITH THE TRANSFER TAPE WITH THE LETTERS STUCK TO IT.







4. HOLD THE TRANSFER SHEET &
LETTERS AWAY FROM THE SURFACE
WITH ONE HAND. USING A
SQUEGEE OR CREDIT CARD APPLY
THE GRAPHIC. TO DO THIS START
IN THE MIDDLE AND PUSH DOWN
WITH THE SQUEGEE THEN SLIDE IT
TO EACH SIDE; DOING THIS PUSHES
THE AIR OUT AND LAYS THE GRAPHICS
ON FLAT. BE SURE TO APPLY AMPLE
PRESSURE.

YOU CAN USE WATER TO APPLY THE GRAPHIC FOR ADDED SECURITY. FILL A WATER BOTTLE WITH WATER & ADD ONE DROP OF DISH SOAP, SHAKE IT UP AND LIGHTLY MIST THE PEELED BACK GRAPHIC. YOU MAY NEED TO WAIT LONGER BEFORE PEELING OFF THE TRANSFER SHEET ONCE APPLIED. AVOID OVER WETTING THE SURFACE OR DECAL & BE SURE YOU DON'T GET THE BACKING PAPER WET WHILE IT IS STILL ON THE DECAL.

5. AFTER YOU APPLY THE DECAL, SLOWLY
PULL BACK THE TRANSFER MATERIAL, PULLING
IT BACK FLAT AGAINST THE SURFACE (TO AVOID
PULLING UP THE LETTERS). YOU SHOULD BE
LEFT WITH JUST YOUR LETTERING. IF YOU HAVE
ANY BUBBLES YOU CAN PRICK THEM WITH AN
XACTO BLADE OR NEEDLE & THEN PUSH THE
AIR OUT OF THE HOLE.

LETTERING CAN BE CLEANED WITH SOAP & WATER OR GLASS CLEANER.

